

# 석면비산 측정 결과 보고서

경남 남해군 서면 정포로269(정포리 732-5)



2019 년 3 월 일



(주)한국석면분석연구회






2. 측정지점 위치도 (측정일 : 2019년 03월 04일)



2. 측정지점 위치도 (측정일 : 2019년 03월 05일)




3. 비산 측정 사진 (측정일 : 2019년 03월 04일)

		
부지경계선1	부지경계선2	부지경계선3

		
부지경계선4	실외	위생설비입구

		
폐기물반출구	폐기물보관지점	-

3. 비산 측정 사진 (측정일 : 2019년 03월 05일)

		
폐기물반출구	-	-